

INSPECTION REPORT

Inspector's Name MIGELY, GREGORY F.		Inspector's Signature			Inspector's ID No. 60702	Report No. 148	Date yy mm dd 2012 08 21		
Railroad/Company Name & Address UNION PACIFIC RR CO.				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Chase Nichols Title Director Track Maintenance Signature _____			
From: City NORTHBROOK		Codes 6280	Destination City & County			Codes	From Latitude		
State IL		17	City NORTHBROOK			6280	From Longitude		
County COOK		C031	County COOK			C031	To Latitude		
Mile Post: From 0017.25 To 0017.75			Inspection Point MAIN TRACK			To Longitude			
Activity Code:	MTW	TOM	RWP						
Units:	1	3	2						
Sub Units:			3						

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] INSPECTED MILWAUKEE SUBDIVISION AT SHERMER DERAILMENT SITE FROM MP 17.25 - 17.75, NO DEFECTS NOTED. TRACK CONDITIONS APPEAR TO BE SUFFICIENT FOR THE MAXIMUM AUTHORIZED SPEED OF 50 MPH.													
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?			